

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 08/24/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 1200, 08/23/12 – 1200, 09/06/12
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Aerial Field Observer	Houston, TX	
8. Activity Log			
Time	Major Events		
	<b>Operational Observation:</b>		
0730	<ul style="list-style-type: none"> <li>Arrived at the ICP</li> </ul>		
0800	<ul style="list-style-type: none"> <li>Began the production of the Situational Photolog for the EPA C&amp;G.</li> </ul>		
0900	<ul style="list-style-type: none"> <li>Attended the EPA C&amp;G meeting.</li> </ul>		
	<ul style="list-style-type: none"> <li>C0.4 Boat launch observed sheen and tar glob.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP5.35 LDB observed sheen and tar glob.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP5.55 LDB sheen and tar globs observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP5.60 LDB sheen observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP5.63 LDB tar globs, rainbow sheen, and silver sheen were observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP5.7 LDB observed a nickel sized tar glob.</li> </ul>		
	<ul style="list-style-type: none"> <li>Observed sheen collecting along the Ceresco Dam control point boom.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP5.45 observed a LSR poling crew.</li> </ul>		
	<ul style="list-style-type: none"> <li>Observed the sweep boat departing the C0.4 boat launch.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP5.0 RDB observed sheen and tar globs.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP4.8 RDB observed a LSR poling crew.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP4.5 sheen was observed.</li> </ul>		
10:30	<ul style="list-style-type: none"> <li>Pulled the boat and relocated to the Shady Bend Campground boat launch.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP15.5 South Mill Pond no sheen was observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP21.25 RDB observed a LSR poling crew</li> </ul>		
	<ul style="list-style-type: none"> <li>MP26.25 RDB no sheen observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP26.0 RDB no sheen observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP24.75 LDB sheen observed quantity of sheen did not meet the criteria for a sheen sweep boat.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP23.10 RDB no sheen observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP21.5 Custer Drive observed sheen.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP21.5 Custer Drive observed sheen sweep operating.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP22.5 LDB observed river bank erosion restoration.</li> </ul>		
	<ul style="list-style-type: none"> <li>MP30.8 LDB no sheen observed.</li> </ul>		
	<ul style="list-style-type: none"> <li>Morrow Lake Delta Booms E &amp; F observed crews working on both booms.</li> </ul>		
	<ul style="list-style-type: none"> <li>Morrow Lake Delta Boom E observed crew removing debris from the boom.</li> </ul>		
	<ul style="list-style-type: none"> <li>Morrow Lake Delta Boom F observed crews performing camera inspection of the curtain.</li> </ul>		
	<ul style="list-style-type: none"> <li>Morrow Lake southern cove observed sheen and tar globs.</li> </ul>		
	<ul style="list-style-type: none"> <li>Morrow Lake northern cove observed sheen and tar globs.</li> </ul>		
14:30	<ul style="list-style-type: none"> <li>Finished with the boat and headed to Ceresco Dam.</li> </ul>		
	<ul style="list-style-type: none"> <li>Ceresco Dam portage put in below Ceresco Dam sheen and tar globs observed.</li> </ul>		
1530	<ul style="list-style-type: none"> <li>Returned to the ICP.</li> </ul>		

	<b>Planning Activities:</b> <ul style="list-style-type: none"><li>• Completed 214</li><li>• Prepared and distributed Daily Situation Unit Photo Log.</li></ul>
9.	Prepared by (Name and Position) Matthew Haak, Situation Unit, USEPA-START